

Seznam lisů :

Poč. ks.	Typ lisu	Max. počet zdvihů	Přestavení beranu (mm)	Zdvih (mm)	Síla (x1000 Kg)	Rozměry stolu (mm)	Rozměry beranu (mm)	Rovnačka	Podavač – tloušťka mat. (mm)	Podavač – šíře pásu (mm)
1	TPO 25	200	60	X.55	2 x 25/19	255 x 505			0,2-3	0 - 80
1	TOP 25 A	300	100	X.70	2 x 25/20	255 x 505			0-1,5	0 - 80
2	LENR 25 A	125	55	VIII.80	25	530 x 370	260 x 280			
1	LENR 40	110	60	VIII.90	40	630 x 430	240 x 220			
2	LENR 40 A	110	60	VIII.90	40	630 x 430	240 x 220	QRM 300/4	0-1,5	0 - 200
1	LEN 40 CA	75 / 50	80	VIII.95	40	660 x 530	400 x 250			
2	LENP 63 A	63	70	10 - 100	63	750 x 500	260 x 270	QRM 300/4	0-1,5	0 - 200
1	LESP 63 A	63	70	10 - 100	63	750 x 500	260 x 270	QRM 300/4	0-3	0-295
2	LEN 63 C	71 / 140	70	10 - 105	63	800 x 630	450 x 280	QRM 300/4	0-3	0 - 200
1	LE 160	45	100	20 - 120	160	1000 x 740	720 x 380			
2	LE 250	45	110	30 - 140	250	1120 x 800	750 x 470			
1	LE 250 A	45	110	30 - 140	250	1120 x 800	750 x 470			
1	LEK 250	45	125	25 - 180	250	1180 x 880	850 x 500			
1	LKT 250	20	100	250	250	1575 x 1150	1400 x 800			
1	LUDR 315	X.65	170	50	315	1800 x 1000	1600 x 900	Max.šíře 1200 mm	0,5 - 3	0 - 1000
1	PELS 315		8	670	315	1300 x 1400	1300 x 1400			